

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.I. (C.P.O) QUALITY CONTROL LABORATORY

Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59. W.F. 14/2020 /187 / 2020-21

dated: 01/01/2021

Name of the Work: Construction of retaining wall for existing nallah from Regina House to Fatima house in ward No. 3 in V.P. Verna of Salcete Taluka.

Sample Sent by :- Assistant Engineer, SD I, WD II , WRD, Rawanfond- Goa.

letter no:- WRD/ SD I/ WD II/ F.Esst/684/2020-21.

Date:- 02-12-2020

Received on: 8/12/2020

Date of Testing: 11/12/2020

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
60/20	Coarse Sand	FM Silt & Clay Grading	2.552 2.30% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
61/20	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate of nominal size blend
62/20	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20 mm & 10 mm metal in 1:1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II , WRD,Rawanfond-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Executive Engineer, WD II, WRD, Rawanfond-Goa.
- 4) Office File.